

Casting a One-Lunger Atlantic Marine Engine

by


Samantha Nicole Castellanos

Submitted to the  
Department of Mechanical Engineering  
in Partial Fulfillment of the Requirements for the Degree of  
Bachelor of Science in Mechanical Engineering

at the

Massachusetts Institute of Technology

June 2016



© 2016 Massachusetts Institute of Technology. All rights reserved.

**Signature redacted**

Signature of Author: \_\_\_\_\_

Department of Mechanical Engineering  
May 6, 2016

**Signature redacted**

Certified by: \_\_\_\_\_

Daniel Braunstein  
Pappalardo Director  
Thesis Supervisor

**Signature redacted**

Accepted by: \_\_\_\_\_

Anette Hosoi  
Professor of Mechanical Engineering  
Undergraduate Officer

# Casting a One-Lunger Atlantic Marine Engine

by

Samantha Castellanos

Submitted to the Department of Mechanical Engineering  
on May 9, 2016 in Partial Fulfillment of the  
Requirements for the Degree of

Bachelor of Science in Mechanical Engineering

## ABSTRACT

Fabrication of a one-lunger Atlantic marine engine for the purposes of developing a curriculum for an advanced fabricating and machining class for the Pappalardo Apprentices at MIT. One-lunger marine engines greatly influenced the fishing cultures of Nova Scotia at the turn of the 20<sup>th</sup> century. Discussion of proper casting practices and terminology in addition to theory of sand types, machinability, engine cycles, and ignition systems. In depth descriptions of basic and advanced casting processes using the ignitor body and piston as examples.

Thesis Supervisor: Daniel Braunstein

Title: (Pappalardo Director

## Table of Contents

<b>1</b>	<b>Introduction.....</b>	<b>1</b>
<b>2</b>	<b>Atlantic One-Lunger Engine Cycle: 2-Stroke .....</b>	<b>2</b>
<b>3</b>	<b>Ignition Systems .....</b>	<b>3</b>
3.1	<b>Make and Break .....</b>	<b>3</b>
3.2	<b>Ignition Magneto.....</b>	<b>4</b>
<b>4</b>	<b>Material Castability and Pouring Temperatures .....</b>	<b>5</b>
<b>5</b>	<b>Machinability and Material Selection .....</b>	<b>8</b>
<b>6</b>	<b>Basic Foundry and Casting Terms.....</b>	<b>11</b>
<b>7</b>	<b>Types of Casting Sand .....</b>	<b>12</b>
7.1	<b>Green Sand.....</b>	<b>12</b>
7.2	<b>Resin Sand.....</b>	<b>14</b>
<b>8</b>	<b>Prepping Part CAD and Model for Casting.....</b>	<b>15</b>
8.1	<b>Before prepping your CAD model for casting: .....</b>	<b>15</b>
8.2	<b>Prepping the CAD model for casting: .....</b>	<b>15</b>
8.3	<b>Creating the Pattern .....</b>	<b>17</b>
<b>9</b>	<b>Casting the Part: Basic Green Sand Casting .....</b>	<b>17</b>
<b>10</b>	<b>Casting the Part: Advanced - Shell Casting the Piston .....</b>	<b>22</b>
10.1	<b>First Attempt.....</b>	<b>23</b>
10.2	<b>Second Attempt.....</b>	<b>26</b>
10.3	<b>Third Attempt.....</b>	<b>30</b>
<b>11</b>	<b>Curriculum Suggestions.....</b>	<b>37</b>
<b>12</b>	<b>Conclusion .....</b>	<b>39</b>
	<b>Acknowledgments .....</b>	<b>39</b>
	<b>References.....</b>	<b>39</b>

## List of Figures


Figure 1: Cover for the Lunenburg Foundry Marine Equipment Catalog [2].	1
Figure 2: Cycle of a 2-stroke one-cylinder combustion engine [7].	3
Figure 3: "Make and break" circuit schematic [4]. Note the inductor is in series with a battery. When the igniter points break, the inductor attempts to create continuous current by creating an arc at the points.	4
Figure 4: Schematic of the Wico Model EK Magneto [5]. The armature is moveable and completes and breaks the magnetic circuit. Changing magnetic fields induce currents in the coils and ultimately a spark.	5
Figure 5: Picture of the Wico Model EK Magneto that was used in a Universal Fisherman one-lunger.	5
Figure 6: Varying strength of green sand mixed with various percentages of southern bentonite and water. Peaks indicate the temper point. [8]	13
Figure 7: Cope is placed on the floor, top side down. The floor and pattern are powdered.	17
Figure 8: Top half of part is placed on the parting surface.	18
Figure 9: A dowel is placed to form the sprue and the cope is filled and rammed with sand in layers.	18
Figure 10: Once the cope is fully filled and rammed, a straight edge is used to scrape off excess sand.	19
Figure 11: Cope is flipped over and powdered with talc.	19
Figure 12: Drag is packed and rammed with sand.	20
Figure 13: The part is removed from the sand with the help of a tapped screw.	20
Figure 14: Cope is placed on top of drag and clamped prior to pouring.	21
Figure 15: After metal has been poured and the part has cooled it is removed from the sand.	21
Figure 16: Full cast of piston with sprue still attached.	22
Figure 17: Mold for piston core (left) and piston pattern (right).	23
Figure 18: Core print made of resin sand, first attempt.	24
Figure 19: The piston pattern is placed in the flask and the flask is filled and rammed with sand.	25
Figure 20: Molten iron is poured into the flask and flames appear from the top. The cast did not appear to fill fully.	25
Figure 21: The failed piston. The core collapsed and the iron filled the hollow part of the core print.	26

Figure 22: Second attempt at creating the core print. The mold is filled fully with sand using a copper tube to create a vent in the middle. ....	26
Figure 23: Pattern of the piston. The seams were plastered and sanded to make it easier to remove the pattern from the sand.....	27
Figure 24: Attempt at creating a shell mold for the pattern. The resin sand cured too quickly and was difficult to secure to the vertical sides of the pattern. ....	28
Figure 25: The shell broke apart only leaving the part surrounding the aligning feature intact.....	28
Figure 26: Left - the cope after the pattern was removed, leaving behind the cavity that would create the piston. Center - the flask is lowered onto the base flask and the core print is aligned. Right - the resulting cast piston. It did not fill with metal fully. ....	29
Figure 27: Cavity of the second attempted piston. The surface finish is good aside from some flash and disturbances near the bosses.....	30
Figure 28: A small box was created in order to attempt a full shell casting of the piston. The pattern is placed in the box and filled with resin sand.....	30
Figure 29: The moustache feature was stuck in the resin sand and broke off when the pattern was being removed from the shell. ....	31
Figure 30: The moustache feature of the piston was epoxied to the pattern. The top was then plastered to fill in any holes and sanded to smooth out the surface. ....	32
Figure 31: The shell casting of the piston fell apart at the boundary between resin sand layers. The first two layers were salvaged and only covered the alignment feature of the pattern. ....	33
Figure 32: The core print was cantilevered into the flask and then the flask was moved onto the base and iron was poured.....	34
Figure 33: Excavating the piston. ....	34
Figure 34: Full cast of the piston (left) and the cavity (right). The finish of the piston cavity is excellent.....	35
Figure 35: A void appeared on the piston. It is located in the vicinity of the piston rings so it should be mostly bored out and should not affect the piston performance. ....	36
Figure 36: The difference in surface finish can be seen. The left side is where green sand met the pattern, the right side is where resin sand met the pattern. ....	36

## 1 Introduction

Look back 150 years and try to imagine the magnitude of excitement and revolution surrounding the boom of the internal combustion engine. The people were in awe. After George Bailey Brayton invented the first safe and practical oil engine in 1872, the American congress foresaw the profound revolution that the internal combustion engine would bring and thought it to be a more revolutionary development “than the invention of the wheel, the use of metals, or the steam engine.” [1]. To put it in perspective, the invention is just as revolutionary as landing on the moon in 1969 or the successful development of human-like artificial intelligence would be in the world we live in today.

By the beginning of the 20th century, gas engines were being created by an estimated 10,000 individual manufacturers all across America [1], and the one-lunger (one cylinder engines) that were used in the fishing cultures of northeastern America greatly influenced those communities. Today, finding one of those engines is a rare event - but this thesis seeks to revive some of the glamour of the past by creating the first CAD model of an Atlantic One-Lunger Marine Engine and fabricating a new one from scratch. The Atlantic Marine Engine was originally manufactured by the Lunenburg Foundry in Nova Scotia, the only surviving company who built two-cycle marine engines [1]. The foundry is also celebrating their 125<sup>th</sup> anniversary this year.



**Figure 1:** Cover for the Lunenburg Foundry Marine Equipment Catalog [2].

The motivation for this paper was to develop a curriculum for a senior advanced fabrication and machining class for the MIT Pappalardo apprenticeship program. The

program selects about 6 juniors, who begin learning more about advanced machining through the fabrication of a small stirling engine. Juniors also learn about speeds and feeds, various tool applications, and how to use indicators for quality control. Juniors who return to the program as seniors then complete an advanced fabrication and machining project, such as is described here. The senior apprentices attempt to build a full scale engine, this first year it was a 2-stroke Atlantic marine engine, and in doing so the apprentices learn complex casting techniques in addition to more machining skills. At any given time, there are about 6 juniors and 6 seniors in the apprenticeship program. In addition to developing machining skills, apprentices are expected to teach and assist sophomores in their first design and manufacturing class, which consists of a robotic competition. Inspiring others to learn about mechanical engineering and proper fabrication techniques while maintaining well-being and happiness is also a vital role of the apprentices. Apprentices seek to be the best of the best and do not back down to a challenge.

## **2 Atlantic One-Lunger Engine Cycle: 2-Stroke**

A 2-stroke engine, with a cylinder containing an internal side passage, has two separate intakes of gas-air mixture going through the engine at any given time. Intake of new gas occurs at the same time as compression of old gas. During the first stroke, the piston moves up compressing the gas mixture, simultaneously taking in more gas mixture into the crankcase. The power stroke then takes over as the gas combusts and pushes the piston down. As the piston moves down, the exhaust port and crankcase passage are exposed, allowing the used gas to exit and the intake gas mixture that has been waiting within the crankcase to move up and above the piston. Then the piston starts going back up and compresses the gas mixture while simultaneously exposing the intake port, allowing more new gas mixture to enter the crankcase. There are 2-stroke engines that lack the passageway between the crankcase and the combustion chamber. In this case, the intake simply moves from the carburetor into the combustion chamber at the same time the exhaust moves out of the chamber. In this scenario, the intake and exhaust ports would be on opposite sides of each other, or at least not side by side. The addition of the passageway allows the intake and exhaust ports to exist next to each other, which makes it easier to design a single and compact manifold that directs the intake and exhaust simultaneously.





Figure 2: Cycle of a 2-stroke one-cylinder combustion engine [7].

### 3 Ignition Systems

#### 3.1 Make and Break

The make and break ignition system centers around two contact points. The contact points, located within the bore of the cylinder (the combustion chamber), “make” and then “break,” creating an arc that ignites the gas and air mixture that already existed within the chamber. The make and break ignition system consists of an electrical circuit with induction coil in series with the ignitor points. The circuit is connected to a battery, thus when the points “make,” or close, and then “break,” the coil creates an


arc between the two points since, fundamentally, inductors require continuous current.




**Figure 3:** “Make and break” circuit schematic [4]. Note the inductor is in series with a battery. When the igniter points break, the inductor attempts to create continuous current by creating an arc at the points.

### 3.2 Ignition Magneto

The magneto ignition system operates on the fundamental principles concerning electromagnetic induction and electromagnetism. A magneto consists of a moveable, laminated steel armature, bar magnets, an iron core, two separate coils, and moveable contact points (breaker points). When the armature is in contact with the iron core, a magnetic flux circuit is created which is energized by a set of bar magnets on the opposite end. When the armature is moved and releases the contact points with the iron core, the magnetic circuit is broken and the magnetic flux flowing within the core begins to diminish. Since the magnetic field is changing, a current is induced within the coils, which wind around the iron core. The resulting current in the primary coil builds up its own magnetic field, and when the primary coil’s current reaches a maximum, the breaker points open the primary circuit, causing the primary’s magnetic field to collapse. The changing of the primary’s magnetic field induces a current within the secondary coils, and generates a high voltage in the two secondary windings, creating an arc at the spark plug and igniting the gas mixture inside the combustion chamber [5, 6].



**Figure 4:** Schematic of the Wico Model EK Magneto [5]. The armature is moveable and completes and breaks the magnetic circuit. Changing magnetic fields induce currents in the coils and ultimately a spark.



**Figure 5:** Picture of the Wico Model EK Magneto that was used in a Universal Fisherman one-lunger.

#### **4 Material Castability and Pouring Temperatures**

Castability of alloys is influenced by their shrinkage factors and freezing range. The freezing range corresponds to the liquidus and solidus temperatures on phase diagrams for specific alloys. Fluidity of an alloy is a measure of the distance to which a metal will flow before solidifying. Generally, high fluidity ensures good castability.

Table 1 shows the shrinkage allowance, approximate liquidus temperature, castability rating, and fluidity rating for various copper-base alloys.

**Table 1:** Foundry properties of the principal copper alloys for sand casting [7].

UNS No.	Common name	Shrinkage allowance, %	Approximate liquidus temperature		Castability rating(a)	Fluidity rating(a)
			°C	°F		
C83600	Leaded red brass	5.7	1010	1850	2	6
C84400	Leaded semired brass	2.0	980	1795	2	6
C84800	Leaded semired brass	1.4	955	1750	2	6
C85400	Leaded yellow brass	1.5–1.8	940	1725	4	3
C85800	Yellow brass	2.0	925	1700	4	3
C86300	Manganese bronze	2.3	920	1690	5	2
C86500	Manganese bronze	1.9	880	1615	4	2
C87200	Silicon bronze	1.8–2.0	...	...	5	3
C87500	Silicon brass	1.9	915	1680	4	1
C90300	Tin bronze	1.5–1.8	980	1795	3	6
C92200	Leaded tin bronze	1.5	990	1810	3	6
C93700	High-lead tin bronze	2.0	930	1705	2	6
C94300	High-lead tin bronze	1.5	925	1700	6	7
C95300	Aluminum bronze	1.6	1045	1910	8	3
C95800	Aluminum bronze	1.6	1060	1940	8	3
C97600	Nickel-silver	2.0	1145	2090	8	7
C97800	Nickel-silver	1.6	1180	2160	8	7

(a) Relative rating for casting in sand molds. The alloys are ranked from 1 to 8 in both overall castability and fluidity; 1 is the highest or best possible rating.

The copper-base casting alloy family is divided into three groups based on the freezing range. Alloys with narrow freezing ranges, a range of 50 °C, are represented in group I; alloys with intermediate freezing ranges, a range of 50 to 110 °C, are represented in group II; and alloys with wide freezing ranges, well over 110 °C, are represented in group III. Table 2 lists the pouring temperatures for alloys of group I, II, and III. The pouring temperatures are above the liquidus temperature for the alloys. Table 3 lists the pouring temperatures for various classes of grey iron. When the freezing range is narrow, or the alloy is in group I, proper attention must be given to gate placement and riser design so that there is no irregular shrinkage in the cast or to prevent cold breaking. Alloys in group III, with wide freezing ranges, form a mushy zone during solidification, which results in interdendritic shrinkage or microshrinkage. When a metal is in the mushy zone of its phase diagram, proper feeding cannot take place and porosity results in the affected sections. Design and riser placement, plus the use of chills, are important in preventing these effects. Maintaining close temperature control of the metal during pouring and providing rapid solidification can also help prevent the pour from entering the mushy zone, but this method limits section thickness and pouring temperatures and also requires a more elaborate gating system that will ensure directional solidification [7]. Directional solidification ensures that solidification of the molten metal occurs in such a manner that liquid metal is always available to feed the portion of the cast that is solidifying. Directional solidification is always desired – it becomes more difficult to achieve the more complex the cast is.

**Table 2:** Pouring temperatures of copper alloys [7].

Alloy type	UNS No.	Light castings		Heavy castings		
		°C	°F	°C	°F	
<b>Group I alloys</b>						
Copper	C81100	1230–1290	2250–2350	1150–1230	2100–2250	
Chromium-copper	C81500	1230–1260	2250–2300	1205–1230	2200–2250	
Yellow brass	C85200	1095–1150	2000–2100	1010–1095	1850–2000	
	C85400	1065–1150	1950–2100	1010–1065	1850–1950	
	C85800	1150–1175	1950–2150	1010–1095	1850–2000	
	C87900	1150–1175	1950–2150	1010–1095	1850–2000	
	C86200	1150–1175	1950–2150	980–1065	1800–1950	
Manganese bronze	C86300	1150–1175	1950–2150	980–1065	1800–1950	
	C86400	1040–1120	1900–2050	950–1040	1750–1900	
	C86500	1040–1120	1900–2050	950–1040	1750–1900	
	C86700	1040–1095	1900–2000	950–1040	1750–1900	
	C86800	1150–1175	1950–2150	980–1065	1800–1950	
	Aluminum bronze	C95200	1120–1205	2050–2200	1095–1150	2000–2100
		C95300	1120–1205	2050–2200	1095–1150	2000–2100
C95400		1150–1230	2100–2250	1095–1175	2000–2150	
C95410		1150–1230	2100–2250	1095–1175	2000–2150	
C95500		1230–1290	2250–2350	1175–1230	2150–2250	
C95600		1120–1205	2050–2200	1095–1205	2000–2200	
C95700		1065–1150	1950–2100	1010–1205	1850–2200	
Nickel bronze	C95800	1230–1290	2250–2350	1175–1230	2150–2250	
	C97300	1205–1225	2200–2240	1095–1205	2000–2200	
	C97600	1260–1425	2300–2600	1205–1315	2250–2400	
	C97800	1315–1425	2400–2600	1260–1315	2300–2400	
	White brass	C99700	1040–1095	1900–2000	980–1040	1800–1900
C99750		1040–1095	1900–2000	980–1040	1800–1900	
<b>Group II alloys</b>						
Beryllium-copper	C81400	1175–1220	2150–2225	1220–1260	2225–2300	
	C82000	1175–1230	2150–2250	1120–1175	2050–2150	
	C82400	1080–1120	1975–2050	1040–1080	1900–1975	
	C82500	1065–1120	1950–2050	1010–1065	1850–1950	
	C82600	1050–1095	1925–2000	1010–1050	1850–1925	
	C82800	995–1025	1825–1875	1025–1050	1875–1925	
	Silicon brass	C87500	1040–1095	1900–2000	980–1040	1800–1900
		C87800	1040–1095	1900–2000	980–1040	1800–1900
Silicon bronze	C87300	1095–1175	2000–2150	1010–1095	1850–2000	
	C87600	1095–1175	2000–2150	1010–1095	1850–2000	
	C87610	1095–1175	2000–2150	1010–1095	1850–2000	
Copper-nickel	C96200	1315–1370	2400–2500	1230–1315	2250–2400	
	C96400	1370–1480	2500–2700	1290–1370	2350–2500	

<b>Group III alloys</b>					
Leaded red brass	C83450	1175–1290	2150–2350	1095–1175	2000–2150
	C83600	1150–1290	2100–2350	1065–1175	1950–2150
	C83800	1150–1260	2100–2300	1065–1175	1950–2150
Leaded semired brass	C84400	1150–1260	2100–2300	1065–1175	1950–2150
	C84800	1150–1260	2100–2300	1065–1175	1950–2150
Tin bronze	C90300	1150–1260	2100–2300	1040–1150	1900–2100
	C90500	1150–1260	2100–2300	1040–1150	1900–2100
	C90700	1040–1095	1900–2000	980–1040	1800–1900
	C91100	1040–1095	1900–2000	980–1040	1800–1900
	C91300	1040–1095	1900–2000	980–1040	1800–1900
Leaded tin bronze	C92200	1150–1260	2100–2300	1040–1175	1900–2150
	C92300	1150–1260	2100–2300	1040–1150	1900–2100
	C92600	1150–1260	2100–2300	1050–1150	1920–2100
	C92700	1175–1260	2150–2300	1065–1175	1950–2150
High-leaded tin bronze	C92900	1095–1205	2000–2200	1040–1095	1900–2000
	C93200	1095–1230	2000–2250	1040–1121	1900–2050
	C93400	1095–1230	2000–2250	1010–1150	1850–2100
	C93500	1095–1205	2000–2200	1040–1150	1900–2100
	C93700	1095–1230	2000–2250	1010–1150	1850–2100
	C93800	1095–1230	2000–2250	1040–1150	1900–2100
	C94300	1095–1205	2000–2200	1010–1095	1850–2000


**Table 3:** Typical pouring temperatures for some classes of gray iron [7]. Shrinkage for grey cast iron is minimal, about 1%.

Class	Approximate liquidus temperature		Pouring temperature								
			Small castings				Large castings				
	°C	°F	Thin sections		Thick sections		Thin sections		Thick sections		
		°C	°F	°C	°F	°C	°F	°C	°F	°C	°F
30	1150	2100	1400	2550	1370	2500	1345	2450	1315	2400	
35	1175	2150	1425	2600	1400	2550	1370	2500	1345	2450	
40	1200	2190	1450	2640	1420	2590	1395	2540	1365	2490	
45	1220	2230	1470	2680	1445	2630	1415	2580	1390	2530	

## 5 Machinability and Material Selection

Machinability is defined as the ease with which materials can be machined. It generally decreases with increasing penetration hardness and yield strength and with increasing ductility. Machinability varies most between material classes or base chemistries, see the table below.

**Table 4:** Machinability for various classes of materials (in order of decreasing machinability) [7].



Most material classes include “free machining” alloys. Free machining materials are 100% machinable materials that do not deteriorate tools or have good chip formation characteristics. The more homogeneous and the finer the grain structures of the material, the easier it is to machine. Alloy additives can also be used to increase machinability but these may compromise material properties that are necessary for certain applications, such as hardness or strength. Some examples of alloy additives include “lead in brasses and steels, sulfur compounds in steels and powder metals, and insoluble metals such as bismuth, selenium, and tellurium in steels” [7].

There are wrought alloys and casting alloys. Wrought alloys are heated and worked after casting, while cast alloys simply just exist as they are cast. Wrought copper alloys optimize strength, ductility (formability), and thermal stability, without inducing unacceptable loss in fabricability, electrical/thermal conductivity, or corrosion resistance. Copper casting alloys offer their own unique composition and property characteristics and are used for their high-thermal and electrical conductivity [7]. Table 1 shows the compositions of wrought and cast copper-base alloys. Wrought iron is a commercial iron that consists of slag (iron silicate) fibers that are entrained in a ferrite matrix. Cast iron consists of more carbon than wrought iron and is very brittle and will fracture before it bends, unlike wrought iron which is malleable.

Grey iron is used for many of the cast parts in the Atlantic engine, such as the cylinder and the piston. It is cheap, strong, and still easily machined when not quenched. Iron has good thermal properties, such as a high coefficient of thermal expansion, which make it a good choice of material for parts that withstand a fair amount of heat. As the material heats up, it is less likely to expand than a part made of an aluminum alloy, thus tolerances can be tighter. Iron also maintains strength at higher temperatures, allowing for thinner geometries and the wear strength of iron is also high. Iron should be poured at a temperature of around 1400 °C. Nowadays, advances in aluminum alloys gave way to aluminum pistons because there are advantages in weight and thermal conductivity – a lighter piston requires less inertia to run and therefore can be more efficient, and high thermal conductivity produces pistons that experience little variation in temperature when in use. The table below describes the main engine parts or systems and their material and method of manufacture.

**Table 5:** Generic classification of copper alloys [7].

Generic name	UNS No.	Composition
<b>Wrought alloys</b>		
Coppers	C10100–C15760	>99% Cu
High-copper alloys	C16200–C19600	>96% Cu
Brasses	C20500–C28580	Cu-Zn
Leaded brasses	C31200–C38590	Cu-Zn-Pb
Tin brasses	C40400–C49080	Cu-Zn-Sn-Pb
Phosphor bronzes	C50100–C52400	Cu-Sn-P
Leaded phosphor bronzes	C53200–C54800	Cu-Sn-Pb-P
Copper-phosphorus and copper-silver-phosphorus alloys	C55180–C55284	Cu-P-Ag
Aluminum bronzes	C60600–C64400	Cu-Al-Ni-Fe-Si-Sn
Silicon bronzes	C64700–C66100	Cu-Si-Sn
Other copper-zinc alloys	C66400–C69900	...
Copper-nickels	C70000–C79900	Cu-Ni-Fe
Nickel silvers	C73200–C79900	Cu-Ni-Zn
<b>Cast alloys</b>		
Coppers	C80100–C81100	>99% Cu
High-copper alloys	C81300–C82800	>94% Cu
Red and leaded red brasses	C83300–C85800	Cu-Zn-Sn-Pb (75–89% Cu)
Yellow and leaded yellow brasses	C85200–C85800	Cu-Zn-Sn-Pb (57–74% Cu)
Manganese bronzes and leaded manganese bronzes	C86100–C86800	Cu-Zn-Mn-Fe-Pb
Silicon bronzes, silicon brasses	C87300–C87900	Cu-Zn-Si
Tin bronzes and leaded tin bronzes	C90200–C94500	Cu-Sn-Zn-Pb
Nickel-tin bronzes	C94700–C94900	Cu-Ni-Sn-Zn-Pb
Aluminum bronzes	C95200–C95810	Cu-Al-Fe-Ni
Copper-nickels	C96200–C96800	Cu-Ni-Fe
Nickel silvers	C97300–C97800	Cu-Ni-Zn-Pb-Sn
Leaded coppers	C98200–C98800	Cu-Pb
Special alloys	C99300–C99750	...

**Table 6:** Atlantic engine material and manufacturing method breakdown by part or system.

Name of Part	Material	Method of Manufacture
Cylinder/Base	Iron	Cast
Piston	Iron	Cast
Piston Rings	Iron, Steel	Machine
Piston Pin	Cold rolled steel	Cast, Forge
Manifold	Iron	Cast
Connecting Rod	Bronze 936	Cast
Crankshaft	Steel	Machine
Ignition System	Iron, Hardened Steel	Cast, Machine, Forge

Cooling System	Brass, Bronze	Cast, Machine
Bearings	Bronze	Cast
Flywheel	Iron	Cast

## 6 Basic Foundry and Casting Terms

- Flask** The metal or wooden box that holds the sand. There is a lip around the rim on both sides of both halves that helps keep the sand in place.
- Cope** Top half of flask.
- Drag** Bottom half of flask.
- Core Print** A mold of the negative space of a part that allows for the creation of cavities or hollow parts. If possible, core prints are made hollow to allow the print to vent properly.
- Pattern** The wooden, plastic, metal, or foam shape that creates the cavity of the sand mold within the flask. The pattern also includes the runner(s).
- Parting Line** The dividing plane of the part that separates the mold into the cope and drag. In some cases the parting line may not be a plane.
- Sprue** The channel that delivers metal to the runner or part. Usually cylindrical or hexagonal, about ½ to 1 inch in diameter. A cup is usually cut out at the top of the sprue to facilitate easy pouring of the metal.
- Runner** The channel that delivers metal from the sprue to the part(s). Runners can be used to connect a casting of multiple parts. Runners can be part of the pattern (which are drafted semicircular or drafted rectangles in cross-section) or cut into the sand before pouring.
- Gate** The location where metal enters the mold for the part. Runners/sprues will be cut from the part at this location.
- Draft** The tapered edges of a pattern that allow for easy removal from the sand. Any surface or edge that would be perpendicular to the parting surface must have draft of 1 or 2 degrees. Remember to include draft on circular parts - anything that is normal to the parting surface is at risk for shearing which has the potential to destroy the sand mold.
- Shrinkage** The reduction in volume as the metal cools, which is a leader factor in casting failures. Shrinkage can distort the cast beyond specified

tolerances or even break the cast all together. A scaling factor must be used on the pattern to ensure the shrunk part is the correct size. See table 1.

<b>Cold Breaking</b>	A.k.a. hot cracking. Casting defect that occurs as a cast cools. Shrinking metal pulls from a still molten area of the cast. If a section is cooling and it tries to pull molten metal from an already frozen section, it can break the part. More common for metals with large shrinkage factors like aluminum, but good patterns account for this.
<b>Riser</b>	An added section to a pattern that fills with molten metal that acts as a reservoir for metal as it cools. Helps debug cold breaking.
<b>Vent</b>	A channel for air. Can be used to get rid of trapped bubbles or vent out inside of a core print.
<b>Green Sand</b>	Most commonly used sand that is reusable and composed of sand, clay, carbons, and water.
<b>No-Bake Sand</b>	Sand molds that don't require heat to cure.
<b>Melting Point</b>	Temperature at which metal becomes molten. Varies for different metals. See table 1.
<b>Pouring Temp.</b>	Temperature at which metal is poured. Hotter than melting point. See table 2 and 3.

## 7 Types of Casting Sand


Green sand is the most common type of casting sand. However, under different circumstances, other types of sand may be used in order to create a better cast. Moreover, cores and more complex casts can be made out of harder sand such as CO<sub>2</sub> sand or resin sand; these sands are known as “no-bake” sands as they do not require heat to cure.

### 7.1 Green Sand

Green sand is the fastest and least expensive of all the molding methods currently in use today. It is a mixture of sand, clay, carbonaceous materials, and water. Although sand casting creates expendable molds, used green sand is almost fully reusable after being rehydrated. Green sand is most commonly composed of washed silica sands.

Clays used in green sand are usually bentonite, a.k.a. montmorillonite, or kaolinite, a.k.a. fireclay, clays. There are two types of bentonite clays: western, or sodium, and southern, or calcium. Western and southern bentonite clays differ in chemical composition and physical behavior. Bentonites are forms of hydrated aluminum

silicate. The structure and nature of the molecules creates clay particles that are flat and allow for the absorption of water – from which the clay expands – between clay plates. The major function of the clay in the green sand is that of a bonding agent by creating clay-water bonds. Bentonites are electrically neutral, thus the water molecules between clay plates and the water molecules absorbed in the sand create a network of adhesive attraction between clay and sand. There is an ideal amount of water, temper water, which bonds all of the clay and sand; it's called the temper point. At the temper point, the sand is at its maximum strength; below this point the sand is not fully bonded, and above this point some water will be in liquid form and not partake in the network of attraction between sand and clay. Figure 6 depicts the corresponding strengths of green sand and percentages of temper water used [8].



**Figure 6:** Varying strength of green sand mixed with various percentages of southern bentonite and water. Peaks indicate the temper point. [8]

The carbonaceous materials serve other purposes than bonding the sand. They can reduce penetration and burn-in, control expansion of the sand, improve dimensional stability of the mold (seacoal only), improve surface finish, and improve the cleanability of the finished casting [8].

Green sand can be optimized for a specific metals and surface finish by choosing the best type or mixture of sand, clay, and carbons and hydrating the sand properly. The composition of green sand used in this application is shown below:

100 lbs sand (olivine sand afs 100)  
 6 lbs southern bentonite  
 2 lbs western bentonite  
 3.5 lbs of water

## 7.2 Resin Sand

Resin sands are used for shell molding and coremaking. Compared to green sand, resin sand shell molds produce castings with greater dimensional accuracy and smoother surfaces. This type of sand can also be used to cast more complex parts. [8]

The resin that was used for the Atlantic engine castings was Kenset R binder. Specifications of Kenset R are detailed in table 7. A TSA, tungstate sulfuric acid, catalyst initiates and speeds the reaction of the binder [9]. The formula for the resin sand used was as follows:

Sand  
 Binder.....2% wt. sand  
 Catalyst.....1% wt. sand

The binder must be mixed in first because once the catalyst comes into contact with the binder, the sand starts to cure and even coating of binder on sand grains is necessary. This resin sand was a “no-bake” sand, meaning no heat was required to cure the molds. The amount of catalyst can be adjusted to either shorten or elongate the curing time. The more catalyst added, the faster the reaction occurs, and the faster the sand cures. The sand is cured when it is a dark, black color. Table 8 compares the advantages and disadvantages of resin sand.

**Table 7:** Specifications of Kenset R, the resin used in the no-bake sand [9].

Specification	Kenset R
Ph	6.0 – 7.0
Viscosity	> 60 cps
Nitrogen	6.5 %
Water	6.5 %
Free Formaldehyde	10 – 12.5 %
Specific Gravity	5% Maximum

Wt. Per Gallon	10 Lbs/Gal
Color	Opaque Orange

**Table 8:** Advantages and disadvantages of resin sand.

<b>Advantages</b>	<b>Disadvantages</b>
Greater dimensional accuracy	Shrinkage
Smoother surfaces	High cost of resin
Less sand required	Toxic substances
Fewer restrictions on casting design	Short working period

## **8 Prepping Part CAD and Model for Casting**

### **8.1 Before prepping your CAD model for casting:**

- 1 Decide on parting line. Will it be a plane or irregular?
- 2 If there is a core, choose a parting line for the core. The parting line for the core does not have to be the same as the regular parting line.
- 3 Decide which half of the part will be placed in the cope and drag. Remember, you want to fill your part with metal from the bottom up, meaning ideally, more of the part should exist within the cope.
- 4 Confirm that there is a flask large enough for your part, if not, make one. Wood glue and nails has been proven to be strong enough for a 13" cube flask. Also create a lip around the rim of the box. The lip helps keep the sand in place when the flask is being flipped over and moved.
- 5 Decide where the gate will be. The gate should be placed in a location that will create the least turbulence during the pour and also allow for the shortest possible length of metal flow.
- 6 Save a copy of the final, machined part - you will be creating many more files during the cast prep and you do not want to overwrite the machined part.

### **8.2 Prepping the CAD model for casting:**

- 1 Add a scaling factor that accounts for shrinkage. Shrinkage factor varies by material. See table 1.

- 2 Delete small through holes and other machined features. Shrink holes that will be cast to allow for post-machining.
- 3 Add material for facing off or turning down.  $\frac{1}{8}$ " is usually enough. Save file as "**cast model.**"
- 4 Save as new copy (copies if core is asymmetrical) and open. Save file as "**core.**" Split part at the core's parting line, which may differ from the patterns parting line. If the core is asymmetrical, complete the steps below on the files of both core halves. If core is symmetrical, create the mirror half of the core mold as a last step.
- 5 Add draft and fillets for the inside of the part only.
- 6 Create the core by adding a new solid body that shares a face with the part's parting line surface. Subtract the part from the solid body. The core should remain.
- 7 Add an alignment feature to the core.
- 8 Make sure the alignment feature is drafted in the proper direction. You should now have two asymmetrical halves of a core with an alignment feature or one half of a symmetrical core.
- 9 Save as new copy and open. Save as "**core mold.**" Create the core mold - add a new solid body that shares a face with the core's parting line. Subtract the core from new solid body. Make sure that at least one section of the mold is left open to allow space to press in the sand. The outward facing surface(s) of the alignment feature(s) is the ideal choice.
- 10 Add pins and/or holes to align the mold halves.
- 11 Open "cast model." Split the cast model in half (save as two files if part is asymmetrical) on the parting line, which may differ from the parting line of the core.
- 12 Save as copy and open. Name "**cast model without core**" and delete the core.
- 13 Create new file and combine "core" with the casting model "cast model without core" - this is the pattern you will cast. Save as "**pattern.**" Note: It may be necessary to add extra material in places where the core and the cast model meet if the draft is not in the same direction. Use your discretion and check the full model carefully for awkward gaps. Using the Solidworks Move/Copy Body feature, properly mate the "cast model without core" and the "core." Look back at the "cast model" to ensure that the measurements are correct.

- 14 Add cylindrical indents to both halves of the pattern to allow for correct alignment across the parting board or surface. If 3D printing the pattern, make it thin walled or hollow so there is less to print.
- 15 Manufacture the “pattern” and the “core mold.”
- 16 There will be two halves of the pattern and two halves of the core mold. Under other circumstances only one half of the flask can be used if there is no parting line.

Note: For parts with no core omit all steps involving the core.

### **8.3 Creating the Pattern**

The pattern can be manufactured using multiple methods. Traditionally, patterns were made of wood, but advances in technology have made other methods available.

3D printing patterns and molds is the least labor intensive method. After parts have been printed, an acetone bath is advised in order to smooth the surface and allow for the pattern’s easy removal from the sand. In order to properly conduct an acetone bath place the part on an aluminum sheet in an air tight container and surround the part with acetone soaked paper towels. Do not let the paper towels touch the 3D printed parts because contact with liquid acetone will melt the pattern. Leave the parts in the bath for about one and a half hours and the surface finish should be smooth and 3D print lines are no longer visible. Patterns can also be made on a wood lathe and with other wood tools and pieced together.

### **9 Casting the Part: Basic Green Sand Casting**

The first part to be cast for the engine was the igniter body. It was a fairly simple part, having no core. The basic steps of casting with green sand are detailed below, using the igniter body as an example, which does not have a core.

**Step One** Powder the parting board and the patterns. Talc powder (baby powder) is used. Note that the floor may be used as the parting surface. Place the cope, upside down, on the parting surface.



**Figure 7:** Cope is placed on the floor, top side down. The floor and pattern are powdered.

**Step Two** Place the part(s) on the parting surface.



**Figure 8:** Top half of part is placed on the parting surface.


**Step Three** Place a dowel and hold upright in place to serve as a sprue. Choose the sprue location carefully. The sprue can also be cut in afterwards using a hollow metal tube.

**Step Four** Add a layer of sand, enough to cover most of the part. Press the sand down, being sure to pack in sand around the part.




**Figure 9:** A dowel is placed to form the sprue and the cope is filled and rammed with sand in layers.

**Step Five** Continue adding layers of sand and packing down the sand. The sand should not comply when pressed. The better the packed sand, the better the cast part. Using a rod or other straight surface, scrape off excess sand. Cut out a cup around the sprue.



**Figure 10:** Once the cope is fully filled and rammed, a straight edge is used to scrape off excess sand.



**Figure 11:** Cope is flipped over and powdered with talc.

**Step Six** Remove the dowel. Flip the cope over. The parting surface of the first half of the part is now visible. Powder the surface with talc.


**Step Seven** Place the bottom half of the part on the parting surface, using the aligning features. Place the drag on top of the cope with the parting surface side down and clamp the flask together.

**Step Eight** Pack sand into the drag as was done in the cope.



**Figure 12:** Drag is packed and rammed with sand.

**Step Nine** Unclamp the flask and remove both halves of the model. If a core is involved, place the core in the mold according to the aligning features. Reclamp the flask and pour the metal.



**Figure 13:** The part is removed from the sand with the help of a tapered screw.



**Figure 14:** Cope is placed on top of drag and clamped prior to pouring.

**Step Ten** Let the cast cool. Quenching after casting is not advised for parts that are post-machined. For large parts, cooling takes place overnight. After the cast has cooled, break it out of the mold and begin machining or evaluate what failed and iterate on the mold design.




**Figure 15:** After metal has been poured and the part has cooled it is removed from the sand.

## 10 Casting the Part: Advanced – Shell Casting the Piston



**Figure 16:** Full cast of piston with sprue still attached.

The piston is a complicated cast. The cylinder beats the piston in terms of volume, complexity, and number of cores, so learning to cast the piston correctly is vital to the understanding and success of the cylinder cast. The first attempt to create the piston was a failure, and as was the second and third. The piston was to be cast without a parting line, placing the sprue directly on the center of the top surface. The pattern and core mold for the piston were 3D printed. Each was split in half and each half took two days to print. The two halves of the piston pattern were then epoxied together and clamped overnight. The core mold had alignment pins on both halves that allowed the mold to be put together easily and accurately, and also helped the halves from bursting open when being packed with sand.



**Figure 17:** Mold for piston core (left) and piston pattern (right).

### **10.1 First Attempt**

First, a flask was created to accommodate the size of the piston and a lip was used in order to help keep the sand in the flask. The flask was a 13" cube, designed to leave at least two inches of sand between the pattern and the flask in any given spot. The flask was made of ½" plywood and did not need any reinforcements, but handles were added to make carrying the flask easier. For larger flasks, reinforcements may be needed in order to keep the sides of the flask from bowing out because the movement of sand in the flask would ruin the cast.



**Figure 18:** Core print made of resin sand, first attempt.

The core print was originally attempted using CO<sub>2</sub> sand, but it was not strong enough and easily broke. The decision was made to use no bake resin sand that solidifies much harder than CO<sub>2</sub> sand. The resin sand was created in 2 kg batches and the use of a kitchen aid mixer. For each batch of sand, the resin and catalyst consists of 3% of the weight of sand – in this case 60 grams. The formula calls for 2/3rds resin, which is mixed in first, and 1/3 catalyst, which gives 40g of resin and 20g of catalyst. Less catalyst can be used in order to slow the curing time of the sand. There were about 7-

10 minutes of working time after the catalyst was mixed in and separate batches of sand don't necessarily bind together if too much time separates them. Remember that with resin sand, time is *always* against you. The resin sand was patted down on the inside of the core mold as to leave the core print hollow to allow for venting. After letting the core print cure, the mold was opened – however the core broke at the interface with the aligning feature, which made it impossible to cantilever the core into the flask and thus more difficult to align the core print properly. It is possible the core print broke because no powder was applied prior to filling it with sand – this is a very important step and must not ever be overlooked.

While the core print cured, the flask was prepared. A 13" cube takes quite a bit of time to fill and ram with sand. Green sand was used and put down in layers and rammed until the flask was full. The sprue was then cut in using a copper tube.



**Figure 19:** The piston pattern in placed in the flask and the flask is filled and rammed with sand.

A vent was then cut in that connected the center of the core print to the top surface of the flask. A base flask (about 13"x13"x5") was also prepared with green sand and the core print was placed on the center of it. The pattern was removed from the main flask and was carefully lowered onto the base flask, making sure that the core properly aligned with the alignment feature on the flask – this was difficult because the flask was very heavy, and it was difficult to see and align the core print while simultaneously lowering the heavy flask. That is why the core was designed to be cantilevered into the flask.



**Figure 20:** Molten iron is poured into the flask and flames appear from the top. The cast did not appear to fill fully.

Now that the flask was fully prepared, iron was melted and poured into the mold. It was instantly known that the cast failed as all of the iron was consumed. The core was not strong enough and imploded, leaving behind a lump of iron on the base flask.



**Figure 21:** The failed piston. The core collapsed and the iron filled the hollow part of the core print.

## 10.2 Second Attempt




**Figure 22:** Second attempt at creating the core print. The mold is filled fully with sand using a copper tube to create a vent in the middle.

Given that the core imploded during the first attempt, the core was filled solid with resin sand using a copper tube to create a vent in its center. The aligning feature now had substantial support, enough to hold up the core print to the weight of the iron being poured. The copper tube was removed once the mold was filled and packed. Since the mold was again not powdered, the core print broke at the interface of the aligning feature and glued back together.



**Figure 23:** Pattern of the piston. The seams were plastered and sanded to make it easier to remove the pattern from the sand.

The pattern for the piston was also cleaned before the second attempt. Plaster was applied and sanded at the seams in order to make the pattern smoother and easier to remove from the flask. Resin sand was applied to the outside of the pattern, after coating it with powder, in an attempt to complete a shell casting of the piston. However, the vertical nature of the piston and the fact that the resin sand begins to cure quickly made it impossible to create a full shell of the pattern. Once the catalyst was added to the resin sand, it needed to be thoroughly mixed to ensure proper bonding. When the sand turned a light, moss, green it was ready to be packed, but once it reached a dark green it became less workable and would not bond to new resin sand, and there were only a few minutes in between shades depending on how much catalyst was added. So in the end, instead of a full shell cast, a shell of the aligning feature was created – which was all that was really necessary. It makes it easier to align the core properly and also keeps the green sand from being bumped and destroyed when inserting the core, since the resin sand shell is much more bonded and hard than the green sand.




**Figure 24:** Attempt at creating a shell mold for the pattern. The resin sand cured too quickly and was difficult to secure to the vertical sides of the pattern.




**Figure 25:** The shell broke apart only leaving the part surrounding the aligning feature intact.

The pattern with the resin sand shell still attached was then packed with green sand in the flask, just like first attempt. The main and base flask were packed and the pattern was removed. The core print was vented through the base flask, unlike the first attempt. Since the core print was broken, the main flask was again lowered on to the base. Iron was melted and poured, but again, the cast appeared to not be fully filled.




**Figure 26:** Left - the cope after the pattern was removed, leaving behind the cavity that would create the piston. Center - the flask is lowered onto the base flask and the core print is aligned. Right - the resulting cast piston. It did not fill with metal fully.

There was not enough metal poured to compensate for the flash, the sprue, and the spillage! The core did work well however, and the surface finish was good. The surface finish on the outside of the piston was poor, but it was not critical since the piston would be turned down.



**Figure 27:** Cavity of the second attempted piston. The surface finish is good aside from some flash and disturbances near the bosses.

**10.3 Third Attempt**



**Figure 28:** A small box was created in order to attempt a full shell casting of the piston. The pattern is placed in the box and filled with resin sand.

A full shell casting was attempted by creating a small box to fill with resin sand, since patting down sand onto the pattern was unsuccessful. A full shell cast of the piston would create a better surface finish on the outside. However, the full shell was unsuccessful. The resin sand shrinks as it cures; if it surrounds a pattern, it will be almost impossible to remove the pattern from the shell. Even after excessive hammering on the copper tube that created the sprue, the pattern would not budge. The box was dismantled and more hammering commenced with no luck. A small hole on the top edge of the pattern was created and hammered and still the pattern would not release. The decision was made to cut half of the top shell off in order to hammer the pattern out more easily, but the entire top layer of the shell broke off. This finally released the pattern, but it was also broken. The moustache shaped feature on the piston was stuck in the resin sand and broke off when the pattern was removed.



**Figure 29:** The moustache feature was stuck in the resin sand and broke off when the pattern was being removed from the shell.

Since the pattern was broken, it needed to be fixed before another pour could occur. The moustache was salvaged and re-epoxied to the pattern. Plaster was then added to smooth out the interface between the moustache and the top surface, and dents that were created during hammering were filled in. The top of the pattern was sanded down until smooth, and the pattern was ready to be cast once again.



**Figure 30:** The moustache feature of the piston was epoxied to the pattern. The top was then plastered to fill in any holes and sanded to smooth out the surface.

Upon returning to the shell mold, more cracks had developed and the shell split at the layers. Since the shell mold was still extremely tight on the pattern, the top two layers that broke off were not glued back together to the rest of the shell and this eased some of the friction that was keeping the pattern stuck. In the end, the shell only covered the aligning feature.



**Figure 31:** The shell casting of the piston fell apart at the boundary between resin sand layers. The first two layers were salvaged and only covered the alignment feature of the pattern.

Like during the other attempts, the core print was created using the resin sand. Powder was coating the mold and the print released whole – the first perfect core. This was ideal because the core could then be cantilevered into the flask.



**Figure 32:** The core print was cantilevered into the flask and then the flask was moved onto the base and iron was poured.

Twenty-four pounds of iron were melted to ensure that there would be a sufficient amount, and there was plenty left over. A full cast of the piston was created. There was an air bubble on the side of the piston, but it was in the vicinity of the piston rings – the bubble should not hurt the efficiency of the piston since the compression rings should seal around the length of the piston. See below for more pictures of the cast piston.

Most important things learned:

- Resin sand has a short period of workability
- Resin sand shrinks
- Separate resin sand layers usually do not bind well
- Resin sand creates a much better surface finish than green sand
- Cores must be hollow and vented but sturdy



**Figure 33:** Excavating the piston.

- Coating patterns with talc powder is a vital step towards a successful cast
- Proper draft is critical and all angles should be filleted if possible



**Figure 34:** Full cast of the piston (left) and the cavity (right). The finish of the piston cavity is excellent.



**Figure 35:** A void appeared on the piston. It is located in the vicinity of the piston rings so it should be mostly bored out and should not affect the piston performance.



**Figure 36:** The difference in surface finish can be seen. The left side is where green sand met the pattern, the right side is where resin sand met the pattern.

## 11 Curriculum Suggestions

A suggested timeline for a 2-stroke engine fabrication is below. In addition to managing time properly and efficiently, various lectures should be held at the beginning of the term. Lectures start the work week. First, students must learn about the combustion engine cycle and the purpose of each subsystem. A demo casting is suggested early in the term to allow for easier understanding of the casting methods, pattern preparation, and terminology, topics which should be taught in conjunction with the demo and reiterated and elaborated on in the lecture following the demo. Students must learn about and be able to identify the foundry tools and casting features that aid the casting process. These include the flask (cope and drag), the crucible, the furnace, personal protective equipment, sand types, draft, sprues, gates, risers, vents, etc. The more the student knows before designing the pattern, the better, and in order to obtain a comprehensive understanding of sand casting methods, metallurgy should also be taught. The more the students learn about the metal and its behavior from its liquid to solid state, the more informed the student will be to make casting decisions and pattern design.

**Table 9:** Suggested schedule.

Weeks	Lectures	Work
1	Engines: two-stroke versus four-stroke, ignition methods, important part identification / function / vital features. Divide up workload: ignition (2), flywheel (1), base (2), cylinder (2), piston (1), connecting rod (1), water pump (1), eccentric (1)	Engine CAD
2	Demo casting: what makes a good mold, good casting practices	Engine CAD End of week: CAD assembly, buy materials
3	Casting do's and don'ts: draft, overhang, gate location, parting line choice, orientation, sand types	Familiarize with casting terminology Pattern CAD Machining Prep/ Start machining
4	Metallurgy, phase diagrams, pouring temperatures	Pattern CAD / Machining

5	Pattern CAD check and review.	Pattern Fabrication / prepare patterns for casting
6	Work Period (9 weeks): Casting, Machining	
7		
8		
9		
10		
11		
12		
13		
14		
15	Finishing touches on parts/ Assembly (run piston through cylinder via an external source for a few days)	
16	Assembly/ official running	

**Table 10:** Allotted pattern making, casting, and machining time during work period of 9 weeks:

Part	Weeks to complete pattern or prep for machining	Weeks to complete cast	Weeks to complete machining / assembly
Piston	2	4	3
Cylinder	4	2 (out of house)	3
Crankshaft	3	N/A	6
Flywheel	4	2 (out of house)	3
Base	4	2 (out of house)	2
Ignition	1	2	6
Water Pump	1	2	6
Eccentric	1	2	6

The schedules provided are a suggestion and will be difficult to keep up with. Casting is a fickle process for beginners, which is why emphasis on the theory of casting is necessary. The more the student knows about casting prior to completing their first pour, the more likely the pour will be successful.

## 12 Conclusion

Casting is an intense process that takes years to master. This thesis aims to help those completing their first casts. The knowledge from this paper aims to assist in the creation of another combustion or steam engine. Time management and collaboration is key, not only between students, but also departments, lab directors, and foundries.

## Acknowledgments

The author would like to thank Daniel Braunstein and the Pappalardo staff for being extremely supportive of this project. Thank you to Mike Tarkarian, head of the Materials Science Foundry, for joining us on this venture.

## References

- [1] Grayson, Stan. "Old marine engines: The World of One Lunger."
- [2] Monchy, Marike Finlay-de and Cope, Karin. "Casting a Legend: The Story of the Lunenburg Foundry." 2002.
- [3] Imgur. <http://i.imgur.com/o5oKsfh.gif>
- [4] Matthews, Harry. 2007. "Ignitions." [www.old-engine.com/maglco.htm](http://www.old-engine.com/maglco.htm)
- [5] GEM Staff. 1978. "Wico Magneto Cycle of Operation (Type EK)." Gas Engine Magazine. <http://www.gasenginemagazine.com/equipment/wico-magneto-cycle-of-operation-type-ek.aspx>
- [6] Wotry, Bud, 1977. "The Remarkable Wico Model EK Magneto." Gas Engine Magazine. Big Rapids, Michigan.
- [7] Davis, J.R.. (1998). Metals Handbook, Desk Edition (2nd Edition). ASM International. Online version available at:  
[https://app.knovel.com/web/toc.v/cid:kpMHDEE004/viewerType:toc/root\\_slug:metals-handbook-desk/url\\_slug:kt010QTQMM](https://app.knovel.com/web/toc.v/cid:kpMHDEE004/viewerType:toc/root_slug:metals-handbook-desk/url_slug:kt010QTQMM)
- [8] ASM International Handbook Committee. (2008; 2010). ASM Handbook, Volume 15 - Casting. ASM International. Online version available at:  
<http://app.knovel.com/hotlink/toc/id:kpASMHVC04/asm-handbook-volume-15/asm-handbook-volume-15>
- [9] Malcom G. Stevens, Inc. "Binders, Core Oil, Flux & Degassers."  
<http://www.mgstevens.com/binders.html>