

Massachusetts Institute of Technology
Department of Electrical Engineering and Computer Science
6.061/6.979 Introduction to Power Systems

Problem Set 8

Issued April 7, 2003
Due April 16, 2003

The first few parts of this problem set are concerned with the same synchronous machine which is characterized by the following parameters:

Number of Poles	p	4
Field to Armature Mutual Inductance (Peak)	M	232 mHy
Armature Phase Self Inductance	L_a	8.2 mHy
Armature Phase-to-Phase Mutual Inductance	L_{ab}	-4.0 mHy
Field Winding Resistance	R_f	20 Ω
Armature Winding Resistance (per phase)	R_a	69 m Ω
Rotational Speed		1800 RPM
Terminal Voltage (RMS, Line-Line)	V_a	480 v
Rated Power		100 kW
Frequency		60 Hz

Problem 1: If this machine is operated synchronously with a balanced *current* source of RMS amplitude 120 A and a field current of 10 A,

1. Calculate and plot a (current) torque-angle curve for this operation.
2. At what (current) torque angle does this machine reach its rated torque as a motor?
3. Calculate and plot terminal *voltage* magnitude (RMS is OK) vs. torque angle.

Problem 2: Now the machine is operating as a synchronous motor, connected to a 480 volt, (RMS, Line-Line) 60 Hz voltage source. Initially, the field current is still 10 A.

1. Calculate and plot the (voltage) torque-angle curve for this operation.
2. At what torque angle does the machine reach its rated torque as a motor?
3. Sketch a phasor diagram for operation at rated torque, showing the same quantities as in Problem 1.
4. What field current is required for operation at rated power and unity power factor?
5. What is the electrical efficiency of the machine when it is operating as a motor at rated power, unity power factor?

Problem 3: for 6.979 In this part of the problem we will examine ways of characterizing operation of this machine. You will probably want to use MATLAB to do the heavy lifting here. Be sure to include limits to machine stability (torque angles do not go beyond 90 degrees), armature current and field current.

1. The *Compounding Curve* for a machine is a chart showing field current required for operation of the synchronous machine as a function of terminal volt-amperes for a fixed value of power factor. Estimate and plot compounding curves for operation of this machine for operation as a motor for power factors of unity, 0.8, 0.5 and zero (mechanically unloaded), both over and under-excited. For the compounding curve you do not need to consider the field current limit.
2. The *Vee curve* is a chart showing armature current vs. field current for operation at fixed real power. Compute and plot vee curves for operation at 20, 40, 60 and 80 kW. Note that you may have to be concerned with stability limits in the underexcited condition and with magnitude of armature and field current. Do not carry the plot beyond 100 kVA in the armature. Assume the field current limit is what you estimated for 0.85 power factor, over-excited operation.

Problem 4 A rough sketch of a 6/4 VRM is shown in Figure 1. The poles are all 30 electrical degrees wide and there are four rotor and six stator poles. A rather highly idealized flux/current characteristic for this machine is shown in Figure 2. Assuming the rather fanciful notion that you can take full advantage of this characteristic and limiting current to 10 A, what average torque can this machine produce?




Figure 1: Rough Sketch of VRM




Figure 2: Maximum and Minimum Flux Characteristics